





Assembling Instructions

Rocking Chair



PARTS

A		1
B		1
C		1
D		1
E		1

F		1
V	M6*30	4 +1 spare
W	M6*35	2 +1 spare
X	M6*40	4 +1 spare
Y		10 +2 spare
Z		1

W x 2
Y x 2

01

80%
100%

V x 2
X x 2
Y x 4

02

80%
100%

V x 2
X x 2
Y x 4

03

80%
100%

done

100%
80%
100%